

Revision history

Revision No.	Date	Description
2.0	Sep. 26, 2013	(1) Update Figure 1-1: JZ4770 Diagram.
1.5	Mar. 28, 2013	(1) Add Table 3-6 (2) Adjust format of chapter 1. (3) Modify relative voltage of AVDCDC in Table 3-1.
1.4	Feb. 17, 2012	(1) Modify 'Min' to '-40' in Table 3-5
1.3	Oct. 17, 2011	(1) Modify the figure of ' JZ4770 pin to ball assignment', including changing the position of 'AUX' and ' WIPER' (2) Add values in the table of ' Absolute Maximum Ratings' (3) Add the chapter of 'Audio codec electronic characteristics' (4) Delete the related content on Hpsense, including delete the 'Hpsense' pin in the table of ' Audio CODEC Pins (19)' (5) Modify 'Hpsense' to 'NC' in the figure of ' JZ4770 pin to ball assignment'
1.2	Aug. 1, 2011	(1) Modify the table of 'Recommended operating conditions for VDDIO/VDDIO _{on} /VDDRTC supplied pins' because of writing error (2) Modify 'Five uarts' to 'Four uarts' in overview spec (3) Update block diagram in overview spec (4) Modify '???' to '181' for GPIO in overview spec (5) Modify '?' to '5' for GPIO in overview spec
1.1	May. 26, 2011	(1) Modify 'Min' of 'V _{RTC} ' to '2.5' and 'Max' of ' V _{RTC} ' to '3.6' in the table of 'Recommended operating conditions for power supplies' (2) Modify 'Power' of 'VBAT' to '1.2V' in the table of ' SAR ADC Pins (9)' (3) Modify the table of 'LVDS Pins (14)' (4) Modify 'loc' of ' WIPER' to 'AA13' and 'loc' of 'AUX' to 'W11' in the table of 'SAR ADC Pins (9)' (5) Add/Delete the function 'FRB1' of PA 23/26/27/28/29 and PB 4/5 (6) Delete 'Uart4' (block and content)
1.0	Mar. 10, 2011	Initial release.